

The latest firmware has been released for Beam Iridium DriveDOCK Extreme Docking Station and has now been made available for download on our website.

The releases include the following:

Supported Firmware:

- Firmware V1.5 - DriveDOCK Extreme
- Firmware V1.2 - PotsDOCK Extreme

Eagle Version: 2.0

- **Released: 29th July, 2015**
- **Supports: Iridium Extreme Handset Firmware HL19004 and Extreme PTT Handset Firmware HP19004**
- **Supports: DriveDOCK Extreme, PotsDOCK Extreme**
- **O/S Supported: Windows 2000, XP(SP3), Vista, 7, 8, 8.1, 10**
- **Installation package includes Eagle software application, USB drivers and firmware**

Overview:

The Eagle allows users to configure a range of software options contained within the DriveDOCK Extreme and PotsDOCK Extreme hardware.

- View the status of the unit
- Configure tracking settings
- Configure POTS settings
- Configure general settings
- Store/Edit/Retrieve docking station settings
- Resetting docking station to the factory defaults
- Modifying supervisor PIN of the unit
- Beam Dock Firmware Upgrade

Revision History:

Version 1.5

- Provides support for Wireless and Corded PTT handset in Phone mode.

Version 1.4

- Support for Push-To-Talk for the DriveDOCK Extreme

Version 1.3

- Improvement - Time module updated to handle new Iridium EPOCH
- Improvement - USB driver support for Windows 8

Version 1.2

- Enhancement - Supports both DriveDOCK and PotsDOCK Extreme
- Enhancement - Includes latest firmware
- Enhancement - DriveDOCK Extreme firmware version 1.2.7594
- Enhancement - PotsDOCK Extreme firmware version 1.1.7594
- Improvement - Improved tracking module
- Improvement - Improved call handling

Version 1.0

- Initial release of Eagle
- Firmware included - Version 1.0.6629

Installation Notes:

Eagle requires Microsoft .Net Framework 3.5, if your PC does not have this installed installation process will download the necessary files needed during installation (Internet access required).